

## **Product Discontinuation Statement**

This document outlines Axis products that have been discontinued or will be discontinued, and indicates the relevant replacement products.

The following products are covered by this statement:

- XF40-Q1765 CLCUS
- XF40-Q1765 -60C CLCUS
- XP40-Q1765 CLCUS
- XP40-Q1765 -60C CLCUS

## **Final Order Date**

The **Final Date** that a Discontinued Product in the list below can be purchased from Axis is **November 16**, **2017**. Please note that an unforeseen increase in demand can cause that the products are out of stock before the final order date.

## **Discontinued Products**

Discontinued Product	Replacement Product
XF40-Q1765 CLCUS [0835-141]	XF40-Q1765 -50C UL [01111-001]
XF40-Q1765 -60C CLCUS [0835-151]	XF40-Q1765 -50C UL [01111-001]
XP40-Q1765 CLCUS [0836-141]	XP40-Q1765 -50C UL [01113-001]
XP40-Q1765 -60C CLCUS [0836-151]	XP40-Q1765 -50C UL [01113-001]

## **Support and RMA Policy**

Axis will continue to give world-class support and RMA service for the Discontinued Products until **November 16**, **2022.** As long as the product is within the warranty period, the RMA service is for free. If the warranty period has expired, the Out Of Warranty price list applies.

Axis RMA service will be based on the Discontinued Products as the primary alternative. When this is not possible, the replacement product will automatically be the alternative stated in the table above.

No additional feature development will be made for the Discontinued Products, effective November 16, 2017.

Lund, Sweden, August 16, 2017

Jesper Olavi Global Product Manager, Axis Communications