



AXIS P3225-VE/-LVE MkII outdoor mounting bracket







AXIS P3245-VE/-LVE outdoor mounting bracket




- 1 Size adjustment of holes (8x)
- 2 New holes (4x)
- 3 Size adjustment of holes (2x)
- 4 Size adjustment of holes (2x). Long holes (2x) removed.
- 5 High screw pillars (4x) moved to same position as on the indoor bracket. Low screw pillars (4x) replaced by 2x and moved to same position as on the indoor bracket.
- 6 New clips (2x) for attaching the camera to the bracket.









Purpose of bracket modifications:

- > To support both horizontally and vertically mounted double gang boxes as well as more Axis accessories, four new holes were added.
- > To preserve robustness, two holes were removed and 12 holes were made slightly smaller.
- > To simplify the installation, four mounting screws were replaced by two clips.
- > Together with the AXIS Conduit Adapters, all new AXIS P32 and AXIS M32 cameras support both 1/2" (M20) and 3/4" (M25) conduits.
- > To synchronize indoor and outdoor accessories, screw pillars and towers were moved to the same positions as the indoor bracket. The brackets of all new AXIS P32 (indoor and outdoor) and AXIS M32 cameras now have the same footprint.

