




**NEW**

AXIS P3245-V/-LV  
indoor mounting bracket

**OLD**

AXIS P3224-V/-LV MkII and AXIS P3225-V/-LV MkII  
indoor mounting bracket



### Purpose of bracket modifications:

- > To support both horizontally and vertically mounted double gang boxes as well as more Axis accessories, four new holes were added.
- > To improve IK rating from IK08 to IK10, two holes were removed and 12 holes were made slightly smaller.
- > Together with the AXIS Conduit Adapters, all new AXIS P32 and AXIS M32 cameras support both 1/2" (M20) and 3/4" (M25) conduits.
- > The brackets of all new AXIS P32 (indoor and outdoor) and AXIS M32 cameras now have the same footprint.