

ACV-128401 Affected Product List

[ACV-128401 Security Advisory](#)

General Information

This document lists the affected products and the firmware version where the vulnerability was patched or state an estimated time plan on when a firmware patch will be made available. Please note that succeeding firmware releases have the patch automatically included as well.

The release notes of a patched firmware will have a reference to ACV-128401 included.
Products that are not listed in this document are not affected.

ACTIVE Track & LTS Track

Products that have an Active Track (FW 8.xx) and a Long Term Support Track (LTS, FW 6.50) will receive firmware patches on both tracks, starting with the LTS track. More information about the ACTIVE Track and LTS Track can be found in the [AXIS Firmware Management White Paper](#).

ACV-128401 Affected Product List



<u>Product Name</u>	<u>Patched Firmware</u>	<u>Product Name</u>	<u>Patched Firmware</u>
AXIS A1001	1.65.1	AXIS M1124	6.50.2.3 / 8.30.1
AXIS A8004-VE	1.65.2	AXIS M1124-E	6.50.2.3 / 8.30.1
AXIS A8105-E	1.65.2	AXIS M1125	6.50.2.3 / 8.30.1
AXIS A9161	1.65.0	AXIS M1125-E	6.50.2.3 / 8.30.1
AXIS A9188	1.65.0	AXIS M1143-L	5.60.1.10
AXIS A9188-VE	1.65.0	AXIS M1144-L	5.60.1.10
AXIS C1004-E	1.81.040.1	AXIS M1145	6.50.2.3
AXIS C2005	1.81.040.1	AXIS M1145-L	6.50.2.3
AXIS C3003-E	1.81.040.1	AXIS M2014-E	5.51.5
AXIS C8033	1.81.040.1	AXIS M2025-LE	8.20.1
AXIS Companion Bullet LE	8.20.1	AXIS M2026-LE	8.20.1
AXIS Companion C360	7.15.2.3	AXIS M2026-LE Mk II	8.10.1.1
AXIS Companion Cube L	8.20.1	AXIS M3004-V	5.51.5
AXIS Companion Cube LW	8.20.1	AXIS M3005-V	5.51.5
AXIS Companion Dome V	8.20.1	AXIS M3006-V	6.50.2.3
AXIS Companion Dome WV	8.20.1	AXIS M3007-P	6.50.2.3
AXIS Companion Eye L	8.20.1	AXIS M3007-PV	6.50.2.3
AXIS Companion Eye LVE	8.20.1	AXIS M3014	5.51.5
AXIS Companion Recorder 4CH	1.20.1	AXIS M3015	7.15.5.1
AXIS Companion Recorder 8CH	1.20.1	AXIS M3016	7.15.5.1
AXIS D2050-VE	7.35.4.2	AXIS M3024-LVE	5.51.5
AXIS F34 Main Unit	6.50.2.3	AXIS M3025-VE	5.51.5
AXIS F41 Main Unit	6.50.2.3	AXIS M3026-VE	6.50.2.3
AXIS F44 Dual Audio Input	6.50.2.3	AXIS M3027-PVE	6.50.2.3
AXIS F44 Main Unit	6.50.2.3	AXIS M3037-PVE	6.55.1
AXIS FA54 Main Unit	6.55.4.5	AXIS M3044-V	8.20.1
AXIS M1004-W	5.51.5	AXIS M3044-WV	8.20.1
AXIS M1013	5.51.5	AXIS M3045-V	8.20.1
AXIS M1014	5.51.5	AXIS M3045-WV	8.20.1
AXIS M1025	5.51.5	AXIS M3046-V	8.20.1
AXIS M1033-W	5.51.5	AXIS M3046-V 1.8mm	8.20.1
AXIS M1034-W	5.51.5	AXIS M3047-P	7.15.2.3
AXIS M1045-LW	8.20.1	AXIS M3048-P	7.15.2.3
AXIS M1054	5.51.5	AXIS M3104-L	8.20.1
AXIS M1065-L	8.20.1	AXIS M3104-LVE	8.20.1
AXIS M1065-LW	8.20.1	AXIS M3105-L	8.20.1
AXIS M1103	5.51.5	AXIS M3105-LVE	8.20.1
AXIS M1104	5.51.5	AXIS M3106-L	8.20.1
AXIS M1113	5.51.5	AXIS M3106-L Mk II	8.10.1.1
AXIS M1113-E	5.51.5	AXIS M3106-LVE	8.20.1
AXIS M1114	5.51.5	AXIS M3106-LVE Mk II	8.10.1.1
AXIS M1114-E	5.51.5	AXIS M3113-R	5.51.5

ACV-128401 Affected Product List



<u>Product Name</u>	<u>Patched Firmware</u>	<u>Product Name</u>	<u>Patched Firmware</u>
AXIS M3113-VE	5.51.5	AXIS P1346-E	5.51.5
AXIS M3114-R	5.51.5	AXIS P1347	5.51.5
AXIS M3114-VE	5.51.5	AXIS P1347-E	5.51.5
AXIS M3203	5.51.5	AXIS P1353	6.50.2.3
AXIS M3203-V	5.51.5	AXIS P1353-E	6.50.2.3
AXIS M3204	5.51.5	AXIS P1354	6.50.2.3
AXIS M3204-V	5.51.5	AXIS P1354-E	6.50.2.3
AXIS M5013	5.51.5	AXIS P1355	5.60.1.10
AXIS M5013-V	5.51.5	AXIS P1355-E	5.60.1.10
AXIS M5014	5.51.5	AXIS P1357	6.50.2.3
AXIS M5014-V	5.51.5	AXIS P1357-E	6.50.2.3
AXIS M5054	6.53.2.1	AXIS P1364	6.50.2.3 / 8.20.1
AXIS M5055	6.53.2.1	AXIS P1364-E	6.50.2.3 / 8.20.1
AXIS M5065	6.53.2.1	AXIS P1365	6.50.2.3
AXIS M5525-E	8.20.1	AXIS P1365 Mk II	6.50.2.3 / 8.20.1
AXIS M7010	5.51.5	AXIS P1365-E	6.50.2.3
AXIS M7011	6.50.2.3	AXIS P1365-E Mk II	6.50.2.3 / 8.20.1
AXIS M7014	5.51.5	AXIS P1367	8.20.1
AXIS M7016	5.51.5	AXIS P1367-E	8.20.1
AXIS P1125-Z	7.10.1.1	AXIS P1368-E	8.20.1
AXIS P1125-ZL	7.10.1.1	AXIS P1405-E	6.50.2.3
AXIS P1126-Z	7.10.1.1	AXIS P1405-LE	6.50.2.3
AXIS P1126-ZL	7.10.1.1	AXIS P1405-LE Mk II	8.20.1
AXIS P1204	5.51.5	AXIS P1425-E	6.50.2.3
AXIS P1214	5.51.5	AXIS P1425-LE	6.50.2.3
AXIS P1214-E	5.51.5	AXIS P1425-LE Mk II	8.20.1
AXIS P1224-E	5.51.5	AXIS P1427-E	6.50.2.3
AXIS P1244	6.50.2.3 / 8.20.1	AXIS P1427-LE	6.50.2.3
AXIS P1245	6.50.2.3 / 8.20.1	AXIS P1428-E	6.50.2.3
AXIS P1254	6.50.2.3 / 8.20.1	AXIS P1435-E	6.50.2.3 / 8.20.1
AXIS P1264	6.50.2.3 / 8.20.1	AXIS P1435-LE	6.50.2.3 / 8.20.1
AXIS P1265	6.50.2.3 / 8.20.1	AXIS P1447-LE	8.20.1
AXIS P1275	6.50.2.3 / 8.20.1	AXIS P1448-LE	8.20.1
AXIS P1280	6.55.2.3	AXIS P3114-I	6.50.3.2
AXIS P1290	6.55.2.3	AXIS P3114-Z	6.50.3.2
AXIS P1325-Z	7.10.1.1	AXIS P3115-I	6.50.3.2
AXIS P1343	5.51.5	AXIS P3115-Z	6.50.3.2
AXIS P1343-E	5.51.5	AXIS P3125-Z	7.10.1.1
AXIS P1344	5.51.5	AXIS P3214-V	6.50.2.3
AXIS P1344-E	5.51.5	AXIS P3214-VE	6.50.2.3
AXIS P1346	5.51.5	AXIS P3215-V	6.50.2.3
		AXIS P3215-VE	6.50.2.3

ACV-128401 Affected Product List



<u>Product Name</u>	<u>Patched Firmware</u>	<u>Product Name</u>	<u>Patched Firmware</u>
AXIS P3224-LV	6.50.2.3	AXIS P3365-VE	6.50.2.3
AXIS P3224-LV Mk II	8.20.1	AXIS P3367-V	6.50.2.3
AXIS P3224-LVE	6.50.2.3	AXIS P3367-VE	6.50.2.3
AXIS P3224-LVE Mk II	8.20.1	AXIS P3374-LV	8.20.1
AXIS P3224-V Mk II	8.20.1	AXIS P3374-V	8.20.1
AXIS P3224-VE Mk II	8.20.1	AXIS P3375-LV	8.20.1
AXIS P3225-LV	6.50.2.3	AXIS P3375-LVE	8.20.1
AXIS P3225-LV Mk II	8.20.1	AXIS P3375-V	8.20.1
AXIS P3225-LVE	6.50.2.3	AXIS P3375-VE	8.20.1
AXIS P3225-LVE Mk II	8.20.1	AXIS P3384-V	6.50.2.3
AXIS P3225-V Mk II	8.20.1	AXIS P3384-VE	6.50.2.3
AXIS P3225-VE Mk II	8.20.1	AXIS P3705-Z	6.40.3.2
AXIS P3227-LV	8.20.1	AXIS P3706-Z	6.40.3.2
AXIS P3227-LVE	8.20.1	AXIS P3707-PE	6.50.2.3
AXIS P3228-LV	8.20.1	AXIS P3904-R	6.50.2.3
AXIS P3228-LVE	8.20.1	AXIS P3904-R Mk II	6.50.2.3
AXIS P3301	5.51.5	AXIS P3905-R	6.50.2.3
AXIS P3301-V	5.51.5	AXIS P3905-R Mk II	6.50.2.3
AXIS P3304	5.51.5	AXIS P3905-RE	6.50.2.3
AXIS P3304-V	5.51.5	AXIS P3915-R	6.50.2.3
AXIS P3314-Z	6.50.3	AXIS P3915-R Mk II	6.50.2.3
AXIS P3314-ZL	6.50.3	AXIS P5414-E	6.50.2.3
AXIS P3315-Z	6.50.3	AXIS P5415-E	6.50.2.3
AXIS P3315-ZL	6.50.3	AXIS P5512	5.51.5
AXIS P3343	5.51.5	AXIS P5512-E	5.51.5
AXIS P3343-V	5.51.5	AXIS P5514	6.50.2.3 / 8.20.1
AXIS P3343-VE	5.51.5	AXIS P5514-E	6.50.2.3 / 8.20.1
AXIS P3344	5.51.5	AXIS P5515	6.50.2.3 / 8.20.1
AXIS P3344-V	5.51.5	AXIS P5515-E	6.50.2.3 / 8.20.1
AXIS P3344-VE	5.51.5	AXIS P5522	5.51.5
AXIS P3346	5.51.5	AXIS P5522-E	5.51.5
AXIS P3346-V	5.51.5	AXIS P5532	5.41.4
AXIS P3346-VE	5.51.5	AXIS P5532-E	5.41.4
AXIS P3353	6.50.2.3	AXIS P5534	5.41.4
AXIS P3354	6.50.2.3	AXIS P5534-E	5.41.4
AXIS P3363-V	6.50.2.3	AXIS P5544	5.41.2.6
AXIS P3363-VE	6.50.2.3	AXIS P5624-E	6.50.2.3
AXIS P3364-LV	6.50.2.3	AXIS P5624-E Mk II	6.50.2.3 / 8.20.1
AXIS P3364-LVE	6.50.2.3	AXIS P5635-E	6.50.2.3
AXIS P3364-V	6.50.2.3	AXIS P5635-E Mk II	6.50.2.3 / 8.20.1
AXIS P3364-VE	6.50.2.3	AXIS P5635-ZE	5.75.3.3
AXIS P3365-V	6.50.2.3	AXIS P7210	5.51.5

ACV-128401 Affected Product List



<u>Product Name</u>	<u>Patched Firmware</u>	<u>Product Name</u>	<u>Patched Firmware</u>
AXIS P7214	5.51.5	AXIS Q1941-E PT Mount	6.55.1.2
AXIS P7216	5.51.5	AXIS Q1942-E	8.20.1
AXIS P7224 Blade	5.51.5	AXIS Q1942-E PT Mount	6.55.1.2
AXIS P8513	5.51.5	AXIS Q2901-E	6.50.2.3
AXIS P8514	5.51.5	AXIS Q2901-E PT Mount	6.50.2.3
AXIS P8524	5.51.5	AXIS Q3504-V	8.20.1
AXIS Q1602	6.50.2.3	AXIS Q3504-VE	8.20.1
AXIS Q1602-E	6.50.2.3	AXIS Q3505-SVE Mk II	8.20.1
AXIS Q1604	6.50.2.3	AXIS Q3505-V	6.50.2.3
AXIS Q1604-E	6.50.2.3	AXIS Q3505-V Mk II	8.20.1
AXIS Q1605-Z	7.10.1.1	AXIS Q3505-VE	6.50.2.3
AXIS Q1614	6.50.2.3	AXIS Q3505-VE Mk II	8.20.1
AXIS Q1614-E	6.50.2.3	AXIS Q3515-LV	8.20.1
AXIS Q1615	6.50.2.3	AXIS Q3515-LVE	8.20.1
AXIS Q1615 Mk II	8.20.1	AXIS Q3517-LV	8.20.1
AXIS Q1615-E	6.50.2.3	AXIS Q3517-LVE	8.20.1
AXIS Q1615-E Mk II	8.20.1	AXIS Q3615-VE	8.20.1
AXIS Q1635	6.50.2.3	AXIS Q3617-VE	8.20.1
AXIS Q1635-E	6.50.2.3	AXIS Q3708-PVE	5.95.4.7
AXIS Q1635-Z	6.50.3	AXIS Q3709-PVE	5.75.1.9
AXIS Q1645	8.20.1	AXIS Q6000-E	6.50.2.3
AXIS Q1647	8.20.1	AXIS Q6000-E Mk II	6.50.2.3
AXIS Q1659	6.56.2.1	AXIS Q6032	5.41.4
AXIS Q1755	5.51.5	AXIS Q6032-C	5.41.3.4
AXIS Q1755-E	5.51.5	AXIS Q6032-E	5.41.4
AXIS Q1765-LE	6.50.2.3	AXIS Q6034	5.41.4
AXIS Q1765-LE PT Mount	6.50.2.3	AXIS Q6034-C	5.41.3.4
AXIS Q1775	6.50.2.3 / 8.20.1	AXIS Q6034-E	5.41.4
AXIS Q1775-E	6.50.2.3 / 8.20.1	AXIS Q6035	5.41.4
AXIS Q1910	5.51.5	AXIS Q6035-C	5.41.4
AXIS Q1910-E	5.51.5	AXIS Q6035-E	5.41.4
AXIS Q1921	5.51.5	AXIS Q6042	6.50.2.3
AXIS Q1921-E	5.51.5	AXIS Q6042-C	6.50.2.3
AXIS Q1922	5.51.5	AXIS Q6042-E	6.50.2.3
AXIS Q1922-E	5.51.5	AXIS Q6042-S	6.50.2.3
AXIS Q1931-E	6.50.2.3	AXIS Q6044	6.50.2.3
AXIS Q1931-E PT Mount	6.50.2.3	AXIS Q6044-C	6.50.2.3
AXIS Q1932-E	6.50.2.3	AXIS Q6044-E	6.50.2.3
AXIS Q1932-E PT Mount	6.50.2.3	AXIS Q6044-S	6.50.2.3
AXIS Q1941-E	8.20.1	AXIS Q6045	5.70.1.7
		AXIS Q6045 Mk II	6.50.2.3
		AXIS Q6045-C	5.70.1.7

ACV-128401 Affected Product List



<u>Product Name</u>	<u>Patched Firmware</u>	<u>Product Name</u>	<u>Patched Firmware</u>
AXIS Q6045-C Mk II	6.50.2.3	AXIS Q8741-E	7.15.3.2
AXIS Q6045-E	5.70.1.7	AXIS Q8741-LE	7.15.3.2
AXIS Q6045-E Mk II	6.50.2.3	AXIS Q8742-E	7.15.3.2
AXIS Q6045-S	5.70.1.7	AXIS Q8742-LE	7.15.3.2
AXIS Q6045-S Mk II	6.50.2.3	AXIS Q8742-E Zoom	7.15.3.2
AXIS Q6052	6.50.2.3 / 8.20.1	AXIS Q8742-LE Zoom	7.15.3.2
AXIS Q6052-E	6.50.2.3 / 8.20.1	AXIS V5914	5.75.1.10
AXIS Q6054	6.50.2.3 / 8.20.1	AXIS V5915	5.75.1.10
AXIS Q6054 Mk II	8.20.1	XF40-Q1765	6.50.2.3
AXIS Q6054-E	6.50.2.3 / 8.20.1	XF40-Q2901	6.55.1.2
AXIS Q6054-E Mk II	8.20.1	XF60-Q2901	6.55.1.2
AXIS Q6055	6.50.2.3 / 8.20.1	XP40-Q1765	6.50.2.3
AXIS Q6055-C	6.50.2.3 / 8.20.1	XP40-Q1942	6.55.1.2
AXIS Q6055-E	6.50.2.3 / 8.20.1	XP60-Q1765	6.50.2.3
AXIS Q6055-S	6.50.2.3 / 8.20.1	D201-S XPT Q6055	6.50.2.3
AXIS Q6114-E	6.50.2.3		
AXIS Q6115-E	6.50.2.3		
AXIS Q6124-E	8.20.1		
AXIS Q6125-LE	8.20.1		
AXIS Q6128-E	6.50.2.3		
AXIS Q6155-E	6.50.2.3 / 8.20.1		
AXIS Q7401	5.51.5		
AXIS Q7404	5.51.5		
AXIS Q7406 Blade	5.51.5		
AXIS Q7411	6.50.2.3		
AXIS Q7414 Blade	5.51.5		
AXIS Q7424-R	5.51.5		
AXIS Q7424-R Mk II	5.51.3.5		
AXIS Q7436 Blade	6.50.2.3		
AXIS Q8414-LVS	6.50.2.3		
AXIS Q8631-E	6.50.2.3		
AXIS Q8632-E	6.50.2.3		
AXIS Q8641-E	6.55.1.2		
AXIS Q8642-E	6.55.1.2		
AXIS Q8655-ZLE	5.55.2.5		
AXIS Q8665-E	6.50.2.3		
AXIS Q8665-LE	6.50.2.3		
AXIS Q8675-ZE	6.20.3.2		
AXIS Q8685-E	6.55.1.3		
AXIS Q8685-LE	6.55.1.3		
AXIS Q8721-E	5.50.2.5		
AXIS Q8722-E	5.50.2.5		