Security Advisory



CVE-2023-21407/12 - 01.08.2023 (v1.0)

Affected products, solutions, and services

• AXIS License Plate Verifier 2.8.3 or earlier

Summary

Diego Giubertoni from <u>Nozomi Networks Inc.</u> has found multiple flaws in the <u>AXIS License Plate Verifier</u> ACAP application. Axis appreciates the efforts of security researchers and ethical hackers on improving security in Axis products, solutions, and services.

CVE-2023-21407 - CVSS: 8.8 High

A broken access control was found allowing for privileged escalation of the operator account to gain administrator privileges.

CVE-2023-21408 - CVSS: 8.4 High

Due to insufficient file permissions, unprivileged users could gain access to unencrypted user credentials that are used in the integration interface towards 3rd party systems.

CVE-2023-21409 - CVSS: 8.4 High

Due to insufficient file permissions, unprivileged users could gain access to unencrypted administrator credentials allowing the configuration of the application.

CVE-2023-21410 - CVSS: 7.2 High

User provided input is not sanitized on the AXIS License Plate Verifier specific "api.cgi" allowing for arbitrary code execution.

CVE-2023-21411 - CVSS: 7.2 High

User provided input is not sanitized in the "Settings > Access Control" configuration interface allowing for arbitrary code execution.

CVE-2023-21412 - CVSS: 7.2 High

User provided input is not sanitized on the AXIS License Plate Verifier specific "search.cgi" allowing for SQL injections.

The severities are calculated by using the CVSSv3.1 scoring system. Learn more about the Common Vulnerability Scoring System here.

Solution & Mitigation

Axis has released a patched version of AXIS License Plate Verifier (2.8.4). Pre-installed versions of AXIS License Plate Verifier are updated on the following products and versions.

AXIS P3245-LVE-3	AXIS OS 11.5.72 & 10.12.193 LTS
AXIS P3265-LVE-3	AXIS OS 11.5.72
AXIS P1445-LE-3	AXIS OS 11.5.72 & 10.12.193 LTS
AXIS P1455-LE-3	AXIS OS 11.5.72 & 10.12.193 LTS
AXIS P1465-I F-3	AXIS OS 11.5.72

Axis Vulnerability Management Portal | Axis Vulnerability Management Policy | Axis Security Notification Service

Security Advisory



CVE-2023-21407/12 - 01.08.2023 (v1.0)

The release notes will state the following: Corrected CVE-2023-21407, CVE-2023-21408, CVE-2023-21409, CVE-2023-21410, CVE-2023-21411, CVE-2023-21412. For more information, please visit the Axis vulnerability management portal.

The latest Axis device software can be found <u>here</u>. The latest version of AXIS License Plate Verifier can be found <u>here</u>. For further assistance and questions, please contact <u>AXIS Technical Support</u>.