

## Product Discontinuation Statement

This document outlines Axis products that will be discontinued and indicates the relevant replacement products.

The following products are covered by this statement:

Discontinued Product	Replacement Product
<b>AXIS M3104-L</b> [0865-XXX]	<b>AXIS M3115-LVE</b> [01604-XXX]
<b>AXIS M3104-LVE</b> [0866-XXX]	<b>AXIS M3115-LVE</b> [01604-XXX]
<b>AXIS M3105-L</b> [0867-XXX]	<b>AXIS M3115-LVE</b> [01604-XXX]
<b>AXIS M3105-LVE</b> [0868-XXX]	<b>AXIS M3115-LVE</b> [01604-XXX]
<b>AXIS M3106-L MKII</b> [01036-XXX]	<b>AXIS M3116-LVE</b> [01605-XXX]
<b>AXIS M3106-LVE MKII</b> [01037-XXX]	<b>AXIS M3116-LVE</b> [01605-XXX]

As of issuing this statement, stock replenishment for concerned products will be phased out. No additional feature development will be made for the discontinued products. LTS firmware tracks will still receive security patches.

- **Final order date: June 30, 2020**

This is the forecasted final date that the discontinued products can be purchased from Axis. Please note that an unforeseen increase in demand can cause products to be out of stock before the final order date.

- **End of Support: June 30, 2025**

Axis will continue to give support and RMA service for 5 years after the final order date. As long as the product is within the warranty period, the RMA service is for free. If the warranty period has expired, the Out of Warranty price list applies. Axis RMA service will be based on the discontinued product as the primary alternative. When this is not possible, the replacement product will automatically be the alternative stated in the table above.

Lund, Sweden, March 28, 2020



Petra Bennermark  
 Global Product Manager, Axis Communications