

## **Product Discontinuation Statement**

This document outlines Axis products that have been discontinued or will be discontinued, and indicates the relevant replacement products.

The following products are covered by this statement:

AXIS P5514-series

## **Final Order Date**

Due to a sales that was impossible to predict the **Final sales Date** for Discontinued Product in the list below is already past.

## **Discontinued Products**

Discontinued Product	Replacement Product
AXIS P5514 50Hz [0754-xx	AXIS M5525-E 50Hz [01145-xxx]
AXIS P5514-E 50Hz [0755-xx	AXIS M5525-E 50Hz [01145-xxx]
AXIS P5514 60Hz [0769-x	XX] AXIS M5525-E 60Hz [01146-xxx]
AXIS P5514-E 60Hz [0771-x)	AXIS M5525-E 60Hz [01146-xxx]
AXIS P5514 50Hz EU [6754-x	xx] TBA
AXIS P5514-E 50Hz EU [6755-x	xx] TBA
AXIS P5514-E 60Hz EU [6771-x	xx] TBA

## Support and RMA Policy

Axis will continue to give world-class support and RMA service for the Discontinued Products until **Jan 22**, **2023**. As long as the product is within the warranty period, the RMA service is for free. If the warranty period has expired, the Out Of Warranty price list applies.

Axis RMA service will be based on the Discontinued Products as the primary alternative. When this is not possible, the replacement product will automatically be the alternative stated in the table above.

No additional feature development will be made for the Discontinued Products, effective Sept 16, 2017

Lund, Sweden, November 07, 2017

Kent Fransson Global Product Manager, Axis Communications