

Product Discontinuation Statement

This document outlines Axis products that will be discontinued and indicates the relevant replacement products.

The following products are covered by this statement:

Discontinued Product	Replacement Product
AXIS P3915-R Mk II [01074-001]	AXIS P3935-LR [01919-001]
AXIS P3915-R Mk II BULK 10 PCS [01074-021]	AXIS P3935-LR BULK 10 PCS [01919-021]
AXIS P3915-R Mk II BULK 50 PCS [01074-031]	N/A
AXIS P3915-R Mk II M12 [01075-001]	AXIS P3935-LR M12 [01932-001]
AXIS P3915-R Mk II M12 BULK 10 PCS [01075-021]	AXIS P3935-LR M12 BULK 10 PCS [01932-021]
AXIS P3915-R Mk II M12 BULK 50 PCS [01075-031]	N/A

As of issuing this statement, stock replenishment for concerned products will be phased out. No additional feature development will be made for the discontinued product, LTS firmware tracks will still receive security patches

- **Final order date**
 - **December 31, 2020**

The forecasted **final date** that the discontinued product/s can be purchased from Axis. Please note that an unforeseen increase in demand can cause products to be out of stock before the final order date.

- **End of Support**
 - **December 31, 2025**

Axis will continue to give support and RMA service for 5 years after the final order date. As long as the product is within the warranty period and it is no warranty void, the warranty terms for RMA still apply. If the warranty period has expired, the Out of Warranty price list applies. Axis RMA service will be based on the discontinued product as the primary alternative. When this is not possible, the replacement product will automatically be the alternative stated in the table above.

Lund, Sweden, June 30, 2020



Erik Mårtensson
Global Product Manager, Axis Communications