

The AXIS 700, with software 1.15, supports these digital copiers and scanners:

Digital Copier/Scanner  (Note: Links in this column are outside the Axis web site)	C o p i e r	Scanner device characteristics							
		B/W	Grayscale	Color	Resolution	Flatbed	ADF	Duplex	Built-in compression
<b>Avision 820C</b>		x	x	x	300	x	x		
<b>Bell+Howell 1000FB/500F</b>		x	x		400	x	x		Option
<b>Bell+Howell 1500FB/6000F</b>		x	x		400	x	x		Option
<b>Bell+Howell 500 FB</b>		x	x		400	x	x		
<b>Bell+Howell 2000D FB</b>		x	x		400	x	x	x	
<b>Canon DR-3020</b>		x			300		x	x	x
<b>Canon GP-200/215</b>	x	x	x		1200	x	x	x	
<b>Canon GP-220/225</b>	x	x	x		1200	x	x	x	
<b>Canon imageRUNNER 200L</b>	x	x	x		1200	x	x		
<b>Canon imageRUNNER 210</b>	x	x	x		1200	x	x	x	
<b>Canon imageRUNNER 330/400</b>	x	x	x		1200	x	x	x	
<b>Canon GP285</b>	x	x	x		1200	x	x	x	
<b>Canon GP335/405</b>	x	x	x		1200	x	x	x	
<b>Fujitsu M3093 DG</b>		x	x		600	x	x	x	Option



<b>HP ScanJet 4c</b>		x	x	x	600	x	Option		
<b>HP ScanJet 4p</b>		x	x	x	300	x	Option		
<b>HP ScanJet 5p</b>		x	x	x	300	x			
<b>HP ScanJet 6100C</b>		x	x	x	600	x	Option		
<b>HP ScanJet 6200C</b>		x	x	x	1200	x	x		
<b>HP ScanJet 6250C</b>		x	x	x	1200	x	x		
<b>HP ScanJet 6300C</b>		x	x	x	1200	x	Option		
<b>HP ScanJet 6350C</b>		x	x	x	1200	x	x		
<b>HP ScanJet 6390C *3</b>		x	x	x	1200	x	x		
<b>HP ScanJet Office (HP ScanJet 4p + ADF)</b>		x	x	x	300	x	x		
<b>Lanier 5040</b>	x	x	x		400	x	x	x	
<b>Lanier 5235</b>	x	x	x		400	x	x	x	
<b>Lanier 5245</b>	x	x	x		400	x	x	x	
<b>Nashuatec D435</b>	x	x	x		400	x	x	x	
<b>Nashuatec D440</b>	x	x	x		400	x	x	x	
<b>Nashuatec D445</b>	x	x	x		400	x	x	x	
<b>Nashuatec SC01</b>		x	x		400	x	x		
<b>Nashuatec SC420</b>		x	x		400	x	x		Option
<b>Océ 3121</b>	x	x	x		1200	x	x	x	
<b>Océ 3122</b>	x	x	x		1200	x	x	x	
<b>Océ 3133</b>	x	x	x		1200	x	x	x	

<b>Océ 3140</b>	x	x	x		1200	x	x	x	
<b>Rex Rotary 2835</b>	x	x	x		1200	x	x	x	
<b>Rex Rotary 2840</b>	x	x	x		400	x	x	x	
<b>Rex Rotary 2845</b>	x	x	x		1200	x	x	x	
<b>Rex Rotary SC01</b>		x	x		400	x	x		
<b>Rex Rotary SC420</b>		x	x		400	x	x		Option
<b>Ricoh Aficio 340</b>	x	x	x		400	x	x	Option	
<b>Ricoh Aficio 350</b>	x	x	x		400	x	x	x	
<b>Ricoh Aficio 401</b>	x	x	x		400	x	x	x	
<b>Ricoh Aficio 450</b>	x	x	x		400	x	x	x	
<b>Ricoh Aficio IS01</b>		x	x		400	x	x		
<b>Ricoh IS420</b>		x	x		400	x	x		Option
<b>Ricoh IS430</b>		x	x		400	x	x		Option
<b>Ricoh IS450</b>		x	x		400	x	x	x	
<b>Savin 9935</b>	x	x	x		400	x	x	x	
<b>Savin 9940</b>	x	x	x		400	x	x	x	
<b>Savin 9945</b>	x	x	x		400	x	x	x	
<b>Sharp AR-250 *2</b>	x	x			600	x	x	x	
<b>Sharp AR-286 *2</b>	x	x			600	x	x	x	
<b>Sharp AR-F331 *2</b>	x	x			600	x	x	x	
<b>Sharp AR-336</b>	x	x			600	x	x	x	

*2									
<b>Sharp AR-405</b> *2	x	x			600	x	x	x	
<b>Sharp AR-S400</b> *2	x	x			600	x	x	x	
<b>Sharp AR-S505</b> *2	x	x			600	x	x	x	
<b>Sharp AR-505</b> *2	x	x			600	x	x	x	

\*1 Currently not supported function/feature

\*2 Sharp offer a kit with mounting bracket, SCSI cable and the AXIS 700

\*3 Transparency adapter currently not supported  
Is your preferred scanning device missing in the list above? Take the opportunity and speak directly to our Product Manager team at [products@axis.com](mailto:products@axis.com) about suggestions of additional scanning devices to be supported by the AXIS 700.